

2017 BMW_Mini BMW Mini 3HB Cooper D		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE XN15	DISPLACEMENT 1,496 cc		
YEAR / REG. 2017/02	MILEAGE 75,435 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. WMWXN320003C48892	DIMENSIONS (L X W X H) 384 × 173 × 143 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
Navigation System			
INSPECTOR REPORT			
Significant repair history (A). Left rear inner panel has repair/distortion (W). Minor scuffs on seat and steering wheel. Repair marks on BO, left front door, and right quarter panel.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H29/2月	メーカー MINI	ドア枚数 3	ボディ形状 コンパクト/ハッチバック	評価点 R
車名 MINI	グレード クーパーD	駆動方式 2WD	4WD	
車種 自家用・その他()	排気量 1500 cc	型式 XN15	燃料 ガソリン	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ハイブリッド()	ボディ ハイブリッド()	走行距離 75,435 km	走行 フロア 6 AT
外装色 ホワイトシルバー/ブラック	カラーNo. AAG・WAG・()	エアコン 有	安全装置 4人	新車のみ O印 を記入
小・中・大 左・中・右	輸入 国産	17,700円	エレクトロニクス TV	その他 TV
セールスポイント CD/バックカメラ/ETC/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/アイドリングストップ/ターボ/ミュージックサーバー				
検査記入欄 修復歴A 左リアインナーW シート擦れ(小) ハンドル擦れ(小) B O & 左前ドア & 右クォーター修理跡				
車体番号 WMWXN320003C48892				
内装 フロント シフト メーター オーディオ その他				