

2017 BMW_Mini BMW Mini 3HB Cooper D		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-XN15	DISPLACEMENT 1,496 cc		
YEAR / REG. 2017/08	MILEAGE 26,900 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE Hatchback		
CHASSIS NO. WMWXN320403C49673	DIMENSIONS (L X W X H) 384 × 173 × 143 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
Navigation System			
INSPECTOR REPORT			
AIS inspected. Minor scuffs on seats and steering wheel, minor exterior scratches. Front bumper bottom has A-grade damage, cloudy headlights.			

初年度登録		メーカー		ドア数		ボディ構造		評価点															
H29 / 8月		MINI		グレード		コンバクトハッチバック		9.5															
		MINI		クーパーD		駆動方式 2WD 4WD																	
車種 自家用・その他()		排気量 1500 CC		型式 LDA-XN15		燃費 都市 高速 平均		内装 A ● C															
乗積 8年8月 / 扶老		燃料 ガソリン ハイブリッド()		ディゼル		後日返品() (保証書・取付金等)																	
走行 口内にヤリ特記人(名・交機)・(盗犯)・(非・支障) + 万 千 + 回 + マイル 26,900		フロア AT																					
外装色 ブリティッシュレーシンググリーン カラーNo. B22		エアドン QW・AG・WAG・()		新備品の品 O印 を記入																			
()		内装色 クロ		乗客定員 4人		PS PW AW サンプルーフ 寒シート																	
シロ		左・右		輸入 区分		走行		リサイクル料															
		17,700円		買取額		エアパック ABS ナビ TV キーレス																	
セールスポイント																							
特記事項 ブリティッシュレーシング LEDヘッドライト PDC (リヤ) マット無し Sキ有																							
検査記入欄 AIS検査済 シート汚れ小 ハンドル汚れ小 外装小傷有 Fバンパ下面Aあり ヘッドライトくもり																							
修復歴 有 (●) <table border="1"> <thead> <tr> <th>W</th> <th>W</th> <th>S</th> <th>C</th> <th>X</th> <th>XX</th> <th>名義</th> </tr> </thead> <tbody> <tr> <td>ボディ</td> <td>エンジン</td> <td>サジ</td> <td>変換</td> <td>交換</td> <td>交換</td> <td></td> </tr> </tbody> </table> 登録地: _____ 月 _____ 日 査でに査度できる 車体番号: WMMWXN3Z0403C49673										W	W	S	C	X	XX	名義	ボディ	エンジン	サジ	変換	交換	交換	
W	W	S	C	X	XX	名義																	
ボディ	エンジン	サジ	変換	交換	交換																		
PW	トボ石	漏A	ワレ	外装	小 ① ② ③	ホイル ④ ⑤ ⑥	エアロ ⑦ ⑧ ⑨	シリアル No.	製造 国														
内装	ゴコ	シミ	ヤブレ	コゴ	コグス	オーチオス	⑩	本	最大積載量														