

2017 BMW_Mini BMW Mini Clubman Cooper D Clubman		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE LR20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2017/07	MILEAGE 47,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Orange	BODY TYPE Station Wagon		
CHASSIS NO. WMWLR920702F95342	DIMENSIONS (L X W X H) 427 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Navigation System		Back Camera	
INSPECTOR REPORT			
Stone chip on front windshield. Interior has dirt, stains, tears, burns, burn holes, audio holes, and scuffs. Exterior has small scratches and A-grade scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式	車種	グレード	駆動方式	ボディタイプ	評価点
H29/7月	MINI	MINI	5	ステーションワゴン	4.5
車名	グレード	駆動方式	ボディタイプ	評価点	
クーパーD クラ ブマン AIS検査済	2WD	4WD			
車種	年式	月	日	登録年	登録月
2000	CC	型式	LR20	型式	型式
車検	年	月	日	車検	車検
走行	マイル	フロア	8	AT	
外装色	カラーNo.	エアコン	Qd・AAG・WAG・()	取説説明書・記録簿・スペアキー	
ボルカニックオレンジ		5人		新車のみ O印 を記入	
小	左・右	左・右	左・右	左・右	左・右
19,440円	19,440円	19,440円	19,440円	19,440円	19,440円
セールスポイント					
バックカメラ/横滑り防止装置(ESC)/運転席エア バック/盗難防止システム/スマートキー/キーレスエント リー/A B S /助手席エアバック/サイドエアバック/H D D ナビ/衝突安全ボディ/アイドリングストップ/ターボ/ ミュージックサーバー/ミュージックプレーヤー接続可					
検査記入欄					
修理歴					
有・無					
A	キズ	U	へこみ/サレ	B	キズ/へこみ
W	腐食跡	S	サビ	C	腐食
X	交換済	Y	交換済	XX	交換済
名義中					
月 日 までに名義できる方					
車体番号					
WMWLR920702F95342					
FW	トランス	エンジン	フル	外装	小
内装	コギレ	シシ	ヤブレ	コギ	コギ
オーディオ	オーディオ	オーディオ	オーディオ	オーディオ	オーディオ
重量	重量	重量	重量	重量	重量
重量	重量	重量	重量	重量	重量
重量	重量	重量	重量	重量	重量
重量	重量	重量	重量	重量	重量