

2017 BMW_Mini BMW Mini Crossover Cooper D Crossover		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-YT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2017/12	MILEAGE 90,061 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WMWYT920103D53373	DIMENSIONS (L X W X H) 432 × 182 × 160 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Roof Rails Adaptive Cruise Control	
INSPECTOR REPORT			
Hail damage repaired, full repaint in the same color.			

初年度登録		メーカー		ドア数		ボディ形式		評価点	
H29 / 12月		車名 MINI		グレード クーパードクロス オーバー		駆動方式 4WD		R	
車種 自家用・その他()		年式 1990 CC		型式 LDA-YT20		国産 国産車		内装 A・⑨・C	
車検 8年12月 / 扶養 口内にヤング4人組(全乗)・過半数(由不明)		総額 ガソリン ハイブリッド() シフト オート		後日返り品() 買取・取付希望() 等					
走行 90,061 km 口外にヤング4人組(全乗)・過半数(由不明) 右前部損傷あり		フロア 8 AT							
外装色 ブラックII カラーNo. ()		エンジン AC・GAG・WAG・()		新備品のみ O印 を記入					
()		内装色 標準装備		5人		サンルーフ 寒シート			
シロ		左・窓		輸入区分		走行		ガラス割れ	
19,090円		買戻金		エアバック		TV		ラジオ	
セールスポイント									
ヒョウ害修理の為 ルーフ ボンネット交換歴あり ゼル車 純正HDDナビ バックカメラ ミラー ETC ミニエキサイトメントPKG アンビエントラ イト 電動トランク スマートキー プッシュスタート									
検査記入欄									
ヒョウ害修理 同色オールペン									
修復歴 ⑨・無									
A	キズ	U	ヘコミサシ	B	キズへハコ	P	色あせ・ベタケ	G	ガラスキ
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済
査読No.									名義
月 日									まで任意でできる。
車体番号									WMWY T920103D53373
FW		①	機A	ワレ	外装	小 ②・③	ホイル ④・⑤	エアロ ⑥・⑦	シリアル ⑧・⑨
内装		⑩	シミ	ヤブレ	コゴ	コガス	オーデイズ	スレ	
基本		値	431mm	幅	182cm	高さ	159cm	最大積載量	