

| 2017 BMW X3 xDrive 20d M Sport |                        | OVERALL               |          |
|--------------------------------|------------------------|-----------------------|----------|
|                                |                        | EXTERIOR              | INTERIOR |
|                                |                        | -                     | -        |
| MODEL CODE                     | DISPLACEMENT           |                       |          |
| LDA-WY20                       | 1,995 cc               |                       |          |
| YEAR / REG.                    | MILEAGE                |                       |          |
| 2017/01                        | 71,900 km              |                       |          |
| DOORS                          | SEATS                  |                       |          |
| 5                              | 5                      |                       |          |
| DRIVETRAIN                     | TRANSMISSION           |                       |          |
| 4WD                            | AT                     |                       |          |
| FUEL                           | STEERING               |                       |          |
| Diesel                         | Right                  |                       |          |
| EXTERIOR COLOR                 | BODY TYPE              |                       |          |
| Black                          | SUV                    |                       |          |
| CHASSIS NO.                    | DIMENSIONS (L X W X H) |                       |          |
| 00V61764                       | 466 × 190 × 168 cm     |                       |          |
| SALES POINTS                   |                        |                       |          |
| Alloy Wheels                   |                        | Roof Rails            |          |
| Leather Seats (Nevada Leather) |                        | Power Tailgate        |          |
| Power Seats (Front)            |                        | Pre-Collision Braking |          |
| Adaptive Cruise Control        |                        | Front Camera          |          |
| Side Camera                    |                        | Back Camera           |          |
| Navigation System              |                        |                       |          |
| INSPECTOR REPORT               |                        |                       |          |
| Minor scratches                |                        |                       |          |