


2017 Daihatsu Move Canbus G Makeup SA2		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA800S	DISPLACEMENT 658 cc		
YEAR / REG. 2017/05	MILEAGE 77,200 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pink	BODY TYPE Kei		
CHASSIS NO. LA800S-0054222	DIMENSIONS (L X W X H) 340 × 148 × 166 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both...		Pre-Collision Braking	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/5月		メーカー ダイハツ		ドア枚数 5	ボディ形状 軽四	評価点 4																				
車名 ムーヴキャンパス		グレード GメイクアップSA2		駆動区分 2WD 4WD																						
車種 自家用・その他()	排気量 660	型式 DBA-LA800S	燃費 CC	内装 A・B・C																						
車検 -年-月/日	燃料 ガソリン	ディーゼル	後日選り品(保証書・取扱説明書等)																							
走行 77,200	マイル	CVT																								
外装色 パールホワイトIII	カラーNo.	エアコン	装備品のみ O印 を記入																							
()	内装色	4人	AW	サンルーフ	革シート																					
左・右	ディーラー	走行	8,790円	エレクトロ	ナビ	TV																				
セールスポイント																										
検査記入欄			修復歴 有 ()																							
外装AU			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/割れ</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換歴</td><td>XX</td><td>交換所</td> </tr> </table>				A	キズ	U	へこみ/割れ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換所
A	キズ	U	へこみ/割れ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換所																	
登録No.			名義中																							
車体番号			LA800S-0054222																							
FW			シリアルNo.																							
内装			最大積載量																							