

2017 Daihatsu Move Canbus X Make Up SA2		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA800S	DISPLACEMENT 658 cc		
YEAR / REG. 2017/07	MILEAGE 44,433 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. LA800S-0062223	DIMENSIONS (L X W X H) 340 × 148 × 166 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
F-grade repair history. Automatic Air Conditioning (AAC). Right front instrument panel distorted. Underbody painted, with rust. Core support distorted. Interior has some scratches and dirt. Rear seat trim cracked. Seat covers installed. Wheel center caps scratched, and various scratches/dents have uneven repairs.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式指定番号		納税印番号		シラカレ番号		評価点	
H 29 7月		ムーヴキャンバス		5		X117777 SA2		R	
型式		DBA-LA800S		総重量		660 cc		燃料	
車種		R 09		1月		車種		自家用	
走行距離		44,433 km		マイル		(交換)		(交換)	
外装色		Lg リーン2		色替無		カラーNo.		色替無	
車台No.		LA800S-0062223		登録No.		8,790円		未納税	
定員		4人		積載量		kg		cm	
輸入車のみ		モデル		年式		輸入区分		ディーラー	
セールスポイント		純正ナビ		フルセグTV		CD		DVD	
注意事項・不具合箇所		F修復歴		冷房はAACです					
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入		右フィンパネヒズミ		下廻りペイント		サビ			
コアサポートヒズミ		室内1部キズ汚れ		Rシートリムワレ		シートカバー取付			
ホイールCPキズ		各キズ凹補修ムラ							
ドアミラー		キズ		ヒビ		ワレ			
工具		無		ジャッキ		無			

