

2017 Daihatsu Move Move 660 X Turbo SA3		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA150S	DISPLACEMENT 658 cc		
YEAR / REG. 2017/08	MILEAGE 41,293 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. LA150S-0125761	DIMENSIONS (L X W X H) 339 × 147 × 163 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Exterior has minor abrasions and dents. Door mirrors have scratches. Interior has dirt/stains, and interior trim has scuffs and scratches. Front windshield has scratches, stone chips, cracks, and repair marks, requiring replacement. General interior condition includes scratches, dirt/stains, burn holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成29年 8月	車名・グレード ムーヴ Xターボ SA3	2WD 4WD	評価点 (4.5)		
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-LA150S	排気量 660 CC	ドア 5 形状 CP		
シフト CAT	冷暖房 AAC	定員 4人	外装 B		
走行 4万1千293 km	燃料 ガソリン	積載 kg	内装 B		
色 ピンク	色コード T29/FC11	セールスポイント (正常に機能するものに限りです)			
R券 8,430 円	スマートキー・ETC ETC・LEDヘッドライト・オートハイビーム				
注意事項申告欄	新備品 (純正品に限り○をつけてください)				
外装 小A・小U	(PS) (PW) (ABS) (7B) (AW)				
ドアミラー キズ	SR ナビ TV カワ				
室内 汚れ	新車保証書 後日品				
内張り すれ	有・無				
内張り キズ	有・無				
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 (キズ・破レ) コゲ・穴・破レ キレ・破レ				
車台番号 0125761	A1				
登録番号	A1				
A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済					
型式指定番号 017964	車台番号 0011	A1			
車体寸法 長さ 339 cm	幅 147 cm	高さ 163 cm			