

2017 Daihatsu Thor Custom Custom G SA?		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M900S	996 cc		
YEAR / REG.	MILEAGE		
2017/09	56,185 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pink	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900S-0013002	373 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			
Left quarter repair history			

出 品 票		保証証番号 18438	制作者番号 0006	シリアル番号			評 価 点		
前年度登録 H29 9 月	車 名 トール	シェッド 5	グレード 1.0 カスタムG SAI	制作者 485 0006	R				
月 次 DBA-M900S		修正量 1000 mm		燃料 灯 音 製造 (C)		内 装 A C			
車種	8 年	10 月	車型	自家用	シフト	DAT	内装	AAC	純正部品 Oをつける 純正ナビ
走行距離	5	6	0	0	0	0	0	0	0
外装色 ブラックマイカ/マゼンタベリーマイカ		色別(注1) 色替無		カラーコード XE2		内装色 色替無		ナビ機器(注外品含む) Oをつける ナビ機器(注外品含む) Oをつける	
車台(年) M900S		車台(月)		0113002		車台(日)		車台(時)	
登録No.		登録No.		9.630		内装No.		内装No.	
登録No.		登録No.		登録No.		登録No.		登録No.	
登録No.		登録No.		登録No.		登録No.		登録No.	
輸入車のメーカー セルシオポイント		輸入車の型式		輸入車名		ディーラー		車台	
例: 衝突軽減装置 社外ナビ バックカメラ 車線逸脱警報 81オーディオ		例: フルセグTV オートクルコン LEDライト フォグランプ オートライト		例: 純正アルミ ETC ステアリングリモコン		例: 純正ナビ		例: ナビ機器	

以 上 事項、不具合発生
 左クォーター修理跡

検査員記入欄：新設装「有」の場合は検査箇所・交換箇所を記入