

2017 Daihatsu Thor Custom Custom G Turbo SA2		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-M900S	DISPLACEMENT 996 cc		
YEAR / REG. 2017/05	MILEAGE 76,750 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. M900S-0006384	DIMENSIONS (L X W X H) 373 × 167 × 174 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Power Sliding Doors (Both Sides) (Both... Cruise Control Navigation System	
INSPECTOR REPORT			

初年度登録	メーカー ダイハツ	ドア数 5	ボディ形状 コンパクトハッチバック	評価点																				
H29 5月	車名 トール	グレード カスタムGターボ SA2	駆動区分 2WD 4WD	4																				
車種 自家用・その他 ()	排気量 1000 cc	型式 DBA-M900S	連供 定式	内装 A・B・C																				
車検 - - 年 月	燃料 ハイブリッド ()	ディーゼル	検日番号 (保証書・取扱説明書 等)																					
☐ 国内にマフラーを記入 (※:交換 ※:追加)																								
走行 7 6 7 5 0 マイル	シフト AT																							
外装色 パールホワイトIII	カラーNo. 036・AAG・WAG・()	装備品のみ O印 を記入																						
()	内装色 色指定は1以内 1色指定と記入	乗車定員 5 人	(F) (P) (AV) サンプル 革シート																					
オプション 左・右 輸入 部分	ディーラー・走行	リサイクル料 9,630円	環境税 エコドライブ	その他 ABS ESP TV モー																				
セールスポイント																								
エアロ純正ナビ衝突安全装置/両側電動スライドドア車 線逸脱防止支援システム/ドライブレコーダー 社外ハッ ドランプ LED/Bluetooth接続ETC																								
修復歴 有・(無)																								
検査記入欄																								
外装AU																								
<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ割れ</td> <td>B</td> <td>キズ・へこみ</td> <td>P</td> <td>色あせ・ボヤ</td> <td>Q</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>修繕跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </table>					A	キズ	U	へこみ割れ	B	キズ・へこみ	P	色あせ・ボヤ	Q	ガラスキズ	W	修繕跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ割れ	B	キズ・へこみ	P	色あせ・ボヤ	Q	ガラスキズ															
W	修繕跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録地 月 日																								
車体番号 M900S-0006384																								
シリアル No.																								
車種 全長 cm 幅 cm 高さ cm 最大積重量																								