

2017 Honda N BOX 660 G Honda Sensing		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-JF3	658 cc		
YEAR / REG.	MILEAGE		
2017/12	58,000 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Green	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1051910	340 × 148 × 179 cm		
SALES POINTS			
Pre-Collision Braking			
INSPECTOR REPORT			
Medium interior dirt, medium carpet dirt, small pillar dirt, dull exterior paint, front windshield stone chip, wheel scuff (A), small door trim scuff (A), exterior line scratches, front windshield repaired.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H29 / 12月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 3.5
車名 N-BOX	グレード 660 G ホンダセンシングス マートキー・リースアップ 車・CDデッキ・	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 660	型式 DBA-JF3	通称 型式	内装 A・B・C
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)	
走行 58,000 km	シフト インパネ	CVT		
外装色 ブリティッシュグリーン・パール	カラーNo. G547P	エアコン	装備品のみ O印 を記入	
()	内装色	4人	AW サンルーフ 革シート	
左・右 左・右	ディーラー・車行	8,110円	エアパック	ナビ TV
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/衝突被害軽減ブレーキ/アイドリングストップ/スマートキー/盗難防止システム/L E Dヘッドライト/横滑り防止装置 (E S C) /ベンチシート/C D /両側スライド				
検査記入欄 A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換車 YX 交換車 登録No. 月 日 まで(名実できる方) 車体番号 JF3-1051910 FW トピ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ 内装 ヨゴレ シス ヤブレ コガ コガ穴 オーディオ穴 スレ				