

2017 Honda N-BOX GL Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF4	658 cc		
YEAR / REG.	MILEAGE		
2017/10	51,982 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF4-1002902	340 × 148 × 182 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Drive...	
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Engine room and radiator support show rust. Minor sagging and scuffs on seats and steering wheel. Side repair marks. Front bumper has paint marks. Both front fenders show screw adjustment marks, and the left fender has a dent. Minor scuffs on rear gate interior trim. Undercarriage has rust and has been undercoated.			

ORIGINAL JAPANESE AUCTION SHEET

H29 / 10月	ホンダ	5	軽四	4
N-BOX		G・Lホンダセンシング		
車種 自家用・その他 ()	排気量 660 cc	型式 JF4	内装 A・⑤・C	
年 月 日	51982	インパネ	AT	
走行 51,982 km	カラーNo. NH875P	エンジン Qd・AAG・WAG・()	新車品のみ・O印を記入	
外装色 ()	内装色 ()	乗車定員 4人	PS PW ④ サンルーフ 革シート	
左・() 輸入車	ディーラー	走行 8,110 km	エレクトロ ④ ④ ④ ④ ④	
セールスポイント				
レーダークルーズ、助手席エアバッグ、ESC、ベンチシート、両側スライド片側電動ドア、Bカメラ、ETC、スマートキー				
検査記入欄				
エンジンルームS有、ラジエータサポートS有、シートへたれ<小>、シートすれ<小>、ハンドルすれ<小>、側面修理跡、Fバンパー塗装跡、右フェンダーネジ調整跡、左フェンダーステーU有、左フェンダーネジ調整跡、リアゲート内張りすれ<小>、下廻りS有、下廻りジョイント塗り				
A キズ B ハミ割れ C キズ・へこみ D 色あせ・汚れ E ガラスキズ W 腐蝕跡 S サゼ C 腐食 X 交換部 XX 交換済				
名義中				
月 日 まで				
JF4-1002902				
シリアル No.				
車種 軽四 年式 平成29年 月 日 最大積載量 kg				