

2017 Honda N-BOX GL Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF1	658 cc		
YEAR / REG.	MILEAGE		
2017/03	83,077 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF1-1946568	340 × 148 × 178 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Exterior: There are noticeable scratches and dents. Interior: There are some noticeable stains. Repair history: No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H29/3月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4	
車名 N-BOX	グレード G・Lパッケージ				
車種 自家用	右	型式 JF1	総排気量 660	燃料 ガソリン	内装 B
年 9年	月 10月	走行 83,077km	マイル 60	AC	重量 Kg
外装色 パールホワイト	カラーNo. ()	リサイクル料 9,790円	車両番号 JF1-1946568		
()	シフト フロア	AT	乗車定員 4人	長さ cm	高さ cm

後付品
(保証書・取扱説明書等)

装備
AW サルーフ ホット
エアロ
セルスポイント

電動スライド ナビTV Bluetooth バックカメラ ETC 衝突軽減ブレーキ スマートキー プッシュスタート
査定員記入欄

※ダメージレベルに関する注意事項
※ダメージレベルは、車体の損傷状況を表す指標であり、必ずしも修理が必要であることを示すものではありません。また、ダメージレベルは、車体の損傷状況を表す指標であり、必ずしも修理が必要であることを示すものではありません。

クオリティグレード説明
外装: 気になるようなキズやヘコミがあります。
内装: 気になる汚れ等が、部分的にあります。
修復歴: 骨格部位に異常はありません。

グー鑑定 コンディションチェックシート
R2922602302

鑑定日 2026年7月23日 内鑑定日

クオリティグレード 内装 ★★★★★ 外装 ★★★★★ 修復歴 無 機能 正常

車両状態の説明

※このシートは、車両の損傷状況を説明するためのものです。必ずしも修理が必要であることを示すものではありません。

※このシートは、車両の損傷状況を説明するためのものです。必ずしも修理が必要であることを示すものではありません。