

2017 Honda Odyssey Absolute Honda Sensing		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RC1	DISPLACEMENT 2,356 cc		
YEAR / REG. 2017/11	MILEAGE 94,929 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Minivan		
CHASSIS NO. RC1-1200375	DIMENSIONS (L X W X H) 484 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/11月	メーカー ホンダ	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価点 4.5
車名 オデッセイ	グレード アブソルート・ホンダセンシング	駆動区分 2WD 4WD		
車種 自家用・その他()	排気量 2400 CC	型式 DBA-RC1	選装 型式	内装 A・B・C
車検 8年11月	抹消 燃料 ハイブリッド	ディーゼ ル	後付選用品(保証書・取扱説明書等)	
走行 94,929 km	シフト フロア	AT		
外装色 プラチナホワイト	カラーNo. ()	エアコン AG・AG・WAG・()	装備品のみのO印を記入	
内装色 ()	乗車定員 7人	サンルーフ 車シート		
左・右 左・右	輸入 区分	ディーラー ・ 銀行	11,870円	販売額 エコノミ
セールスポイント 両側パワースライドドア ホンダセンシング 純正9型ナビ レーダークルコン コーナーセンサー 衝突軽減レーンアシスト 全方位カメラ パワーシート ビルトインETC2.0 アイドリングストップ フルセグ				
検査記入欄				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換部 YX 交換部				
登録No. 月 日 名義中				
車体番号 RC1-1200375				
シリアルNo.				
FW トビ	備A	ワレ	外装 小	ホイール
内装 白	シシ	ヤブレ	コガ	コガ穴
オーディー穴				
取組				
長さ cm 幅 cm 高さ cm 最大積重量 Kg				