

2017 Honda Shuttle Hybrid Hybrid Z		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GP7	DISPLACEMENT 1,496 cc		
YEAR / REG. 2017/03	MILEAGE 33,383 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Station Wagon		
CHASSIS NO. GP7-1114233	DIMENSIONS (L X W X H) 440 × 170 × 155 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Roof Rails Cruise Control Navigation System	
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small ones remain. Interior: Some noticeable stains and dirt are present. Repair History: No frame damage.			

ORIGINAL JAPANESE AUCTION SHEET

青森内のカー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H29/3月	メーカー ホンダ	ドア数 5	ボディ形状 ステーションワゴン	評価点 4
車種 シャトル	グレード ハイブリッドZ	駆動方式 GP7	走行距離 1500	内装 B
年 -	月 -	日 -	リサイクル料 3,383	マイル 60
外装色 レッドM	カラーNo. ()	リサイクル料 9,600円	販売店 GP7-1114233	重量 Kg
()	シフト フロア 7 AT	乗車定員 5人	長さ cm	幅 cm

車検返却日
() 保証書・取扱説明書等

装備
H29/3月 ナビ TV

セールスポイント
ワンオーナー・DVRバックカメラ・TC機構
り防止装置(ESC)・運転席エアバック
シート・A・B・S・5速手動エアバック・サイド
エアバック・衝突安全ボディ・アイドリング
ストップ・オートクルーズコントロール
シートヒーター
常設乗員入場

※ダメージレベルに関する注意事項
ダメージレベルは、車検時の状態を基準として評価されています。ダメージレベルは、車検時の状態を基準として評価されています。ダメージレベルは、車検時の状態を基準として評価されています。

クオリティグレード説明
外装: 劣化するキズやホコリは補修済みですが、小さなキズやホコリが残っています。
内装: 劣化する汚れ等が、部分的にあります。

修理歴: 骨格部位に異状はありません。

車検返却の保証は、停止状態で実施できる範囲で行っています。

車検返却の保証は、停止状態で実施できる範囲で行っています。