

2017 Honda Step Wagon Spada Spada Honda Sensing		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RP3	DISPLACEMENT 1,496 cc		
YEAR / REG. 2017/12	MILEAGE 81,814 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. RP3-1205893	DIMENSIONS (L X W X H) 476 × 170 × 184 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Power Sliding Doors (Both Sides) (Both... Adaptive Cruise Control	
INSPECTOR REPORT			
R-grade repair history: Right panel replaced, Right floor distortion.			

初年度登録	メーカー ホンダ	ドア数 5	ボクサー機	ミニバンワンボックス	評価点
H29 / 12月	車名 ステップワゴンスパード	グレード スパード ホンダセ ンシング	駆動方式 4WD	R	
車種 自家用・その他（ ）	排気量 1500	型式 DBA-RP3	燃費 都市	内装 A・G・C	
年次 8年12月	抹消	燃料 ガソリン	ディーゼル	後日選り込み ()	()
走行 口内にマーク等記入(※)交換 (※)盗品 (※)不明	シフト オート	材料 ハイブリッド	AT	Sキー有り	
外装色 クロ	カラーNo. (NH812P)	エンジン QD・AAD・WAD・()	新備品のみのO印を記入		
()	内装色 ()	重量定員 7人			
シロ	左・右	輸入 区分	ディーラー	走行	リサイクル料
					10,230円
セールスポイント					
両側パワースライドドア、純正9インチナビ、フルセグTV、バックカメラ、ヒルトインETC、LEDヘッドライ、ホンダエンジンガード、レザー調シートカバー、スマートキー、プッシュスタート、パドルシフト					
検査記入欄					
R修復歴					
RパネルXX、Fフロアビズミ					
修復歴					
A	KZ	U	ヘコキスアリ	B	KZヘコキス
W	補修部	S	サビ	C	腐食
X	交換部	Y	交換部	XX	交換部
登録年月					
月					
日までに変更できる。					
車体番号 R P3-1205893					
FW	トピ石	ワレ	外装	小	オイル
内装	ゴゴ	シミ	ヤブレ	コゴ	コーナ