

2017 Hybrid LS500h Version L 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DAA-GVF55	3,456 cc		
YEAR / REG.	MILEAGE		
2017/11	120,566 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GVF55-6000925	524 × 190 × 146 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats		Adaptive Cruise Control	
Navigation System		Lexus LS Premium Sound System (12 s...	
INSPECTOR REPORT			
Interior burn mark			

初年度登録		メーカー		ドア枚数		ボディ仕様		年価点																																									
H29 / 11月		レクサス		LS		ハイブリッドLS500hバージョンL4WD		2WD																																									
								4WD																																									
車種		用途		型式		型式区分		内装																																									
乗用車・その他		3500		DAA-GVF55				A・B・G																																									
年表		燃料		ディーゼル		償還月数 (保証書・取扱説明書等)																																											
- 年 月		ガソリン		ハイブリッド																																													
走行		口内にマーク付人物入(乗・交換)・(盗取)・(中・不審)		シフト																																													
120,566		左前座席に1人(乗・交換)・(盗取)・(中・不審)		AT																																													
外装色		カラーNo.		エンジン																																													
ブラック		223		AD・GDO・WAG・()																																													
()		内装色		標準定員		新着品のみ O印 を記入																																											
()		()		人		☐ ☐ ☐ ☐ ☐ ☐																																											
シロ		左・右		輸入区分		ディーラー		走行																																									
ディーラー		ディーラー		ディーラー		ディーラー		ディーラー																																									
15,780円		15,780円		15,780円		15,780円		15,780円																																									
セールスポイント		MOPマークレインセンオーディオ、専用セミアニリン白革エアシート、デジタルインナーミラー、オプション20インチAW、カラヘッドアップディスプレイ、パノラミックビューモニター、BSM、ドライブレコーダー、パワートランク、メーカー12.3インチナビ、三眼LEDヘッド																																															
特記事項		スタッドレスト		修復歴 ☐																																													
検査記入欄		ルーム内コゲ		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ・凹み</td> <td>B</td> <td>キズ・へこみ</td> <td>P</td> <td>色あせ・色むら</td> <td>G</td> <td>ガラス割れ</td> </tr> <tr> <td>W</td> <td>傷跡</td> <td>S</td> <td>サビ</td> <td>O</td> <td>腐食</td> <td>X</td> <td>交換品</td> <td>XX</td> <td>交換済</td> </tr> <tr> <td colspan="10">査読No. _____ 月 _____ 日 家で名義でできる</td> </tr> <tr> <td colspan="10">車体番号 GVF55-6000925</td> </tr> </table>						A	キズ	U	へこみ・凹み	B	キズ・へこみ	P	色あせ・色むら	G	ガラス割れ	W	傷跡	S	サビ	O	腐食	X	交換品	XX	交換済	査読No. _____ 月 _____ 日 家で名義でできる										車体番号 GVF55-6000925									
A	キズ	U	へこみ・凹み	B	キズ・へこみ	P	色あせ・色むら	G	ガラス割れ																																								
W	傷跡	S	サビ	O	腐食	X	交換品	XX	交換済																																								
査読No. _____ 月 _____ 日 家で名義でできる																																																	
車体番号 GVF55-6000925																																																	
FW		L21		L21		L21		L21																																									
L21		L21		L21		L21		L21																																									
L21		L21		L21		L21		L21																																									
L21		L21		L21		L21		L21																																									