

|                                                                                                                                                |                                              |                                              |          |
|------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------|----------|
| 2017 SUBARU Impreza G4 2.0i-L<br>EyeSight                                                                                                      |                                              | OVERALL                                      |          |
|                                                                                                                                                |                                              | 3.5                                          |          |
|                                                                                                                                                |                                              | EXTERIOR                                     | INTERIOR |
|                                                                                                                                                |                                              | -                                            | -        |
| MODEL CODE<br>GK7                                                                                                                              | DISPLACEMENT<br>1,995 cc                     |                                              |          |
| YEAR / REG.<br>2017/11                                                                                                                         | MILEAGE<br>38,531 km                         |                                              |          |
| DOORS<br>4                                                                                                                                     | SEATS<br>5                                   |                                              |          |
| DRIVETRAIN<br>4WD                                                                                                                              | TRANSMISSION<br>AT                           |                                              |          |
| FUEL<br>Petrol                                                                                                                                 | STEERING<br>Right                            |                                              |          |
| EXTERIOR COLOR<br>Silver                                                                                                                       | BODY TYPE<br>Sedan                           |                                              |          |
| CHASSIS NO.<br>GK7-005268                                                                                                                      | DIMENSIONS (L X W X H)<br>463 × 178 × 146 cm |                                              |          |
| SALES POINTS                                                                                                                                   |                                              |                                              |          |
| Alloy Wheels<br>Cruise Control                                                                                                                 |                                              | Adaptive Cruise Control<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                               |                                              |                                              |          |
| Exterior: There are noticeable scratches and dents. Interior: There are some noticeable stains. Repair history: No abnormalities in the frame. |                                              |                                              |          |

[illegible]