


|                                                                  |                                              |                         |          |
|------------------------------------------------------------------|----------------------------------------------|-------------------------|----------|
| 2017 SUBARU Impreza Sport 1.6 i-L<br>EyeSight EyeSight Safety+   |                                              | OVERALL                 |          |
|                                                                  |                                              | 4                       |          |
|                                                                  |                                              | EXTERIOR                | INTERIOR |
|                                                                  |                                              | -                       | -        |
| MODEL CODE<br>DBA-GT2                                            | DISPLACEMENT<br>1,599 cc                     |                         |          |
| YEAR / REG.<br>2017/12                                           | MILEAGE<br>35,000 km                         |                         |          |
| DOORS<br>5                                                       | SEATS<br>5                                   |                         |          |
| DRIVETRAIN<br>2WD (FF)                                           | TRANSMISSION<br>AT                           |                         |          |
| FUEL<br>Petrol                                                   | STEERING<br>Right                            |                         |          |
| EXTERIOR COLOR<br>Black                                          | BODY TYPE<br>Hatchback                       |                         |          |
| CHASSIS NO.<br>GT2-031752                                        | DIMENSIONS (L X W X H)<br>446 × 178 × 148 cm |                         |          |
| SALES POINTS                                                     |                                              |                         |          |
| Alloy Wheels<br>Cruise Control                                   |                                              | Adaptive Cruise Control |          |
| INSPECTOR REPORT                                                 |                                              |                         |          |
| Minor exterior scratches, partial paint peeling on rear spoiler. |                                              |                         |          |

ORIGINAL JAPANESE AUCTION SHEET

|                                                                                                                                                       |             |               |                      |                    |                                                 |                           |           |            |               |             |            |                                                                                                                                                                                                     |            |               |            |                    |                                                 |          |          |          |          |          |          |              |            |               |            |                    |                                                 |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|---------------|----------------------|--------------------|-------------------------------------------------|---------------------------|-----------|------------|---------------|-------------|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------|------------|--------------------|-------------------------------------------------|----------|----------|----------|----------|----------|----------|--------------|------------|---------------|------------|--------------------|-------------------------------------------------|
| 初年度登録<br>H29<br>12月                                                                                                                                   | メーカー<br>スバル | ドア枚数<br>5     | ボディ形状<br>コンパクトハッチバック | 駆動方式<br>2WD<br>4WD | グレード<br>1.6i-Lアイサイトアイサイトセーフティ+アイサイトVer3/BSM/LED | 年<br>9                    | 月<br>2    | 日<br>35    | 時<br>00       | 分<br>00     | 秒<br>00    | 走行<br>000000                                                                                                                                                                                        | 燃料<br>ガソリン | エンジン<br>ディーゼル | 変速機<br>CVT | 駆動方式<br>2WD<br>4WD | グレード<br>1.6i-Lアイサイトアイサイトセーフティ+アイサイトVer3/BSM/LED | 年<br>9   | 月<br>2   | 日<br>35  | 時<br>00  | 分<br>00  | 秒<br>00  | 走行<br>000000 | 燃料<br>ガソリン | エンジン<br>ディーゼル | 変速機<br>CVT | 駆動方式<br>2WD<br>4WD | グレード<br>1.6i-Lアイサイトアイサイトセーフティ+アイサイトVer3/BSM/LED |
| 車種<br>自家用・その他                                                                                                                                         | 排気量<br>1600 | 型式<br>DBA-GT2 | 通称<br>GT2            | 内装<br>A・B・C        | 後付部品<br>（保証書・取扱説明書等）                            | 外装色<br>クリスタルブラック・シリカ（D4S） | 内装色<br>（） | 乗車定員<br>5人 | 価格<br>11,870円 | オプション<br>（） | 整備記録<br>（） | 修理履歴<br>（）                                                                                                                                                                                          | 車検<br>（）   | 納期<br>（）      | 納期<br>（）   | 納期<br>（）           | 納期<br>（）                                        | 納期<br>（） | 納期<br>（） | 納期<br>（） | 納期<br>（） | 納期<br>（） | 納期<br>（） | 納期<br>（）     | 納期<br>（）   | 納期<br>（）      | 納期<br>（）   | 納期<br>（）           | 納期<br>（）                                        |
| セールスポイント<br>キーレスエントリー/ABS/運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/衝突被害軽減ブレーキ/ETC/アイドリングストップ/スマートキー/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置（ESC）/フルフラットCD/障害物センサー |             |               |                      |                    |                                                 |                           |           |            |               |             |            |                                                                                                                 |            |               |            |                    |                                                 |          |          |          |          |          |          |              |            |               |            |                    |                                                 |
| 検査記入欄<br>外装小傷 Rスポイラー一部Pハゲ                                                                                                                             |             |               |                      |                    |                                                 |                           |           |            |               |             |            | A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ<br>W 補修跡 S サビ C 腐食 X 交換品 XX 交換済<br>登録No. 月 日 までに名義できる方<br>車体番号 GT2-031752<br>FW トピ石 傷A フレ 外装 小 ホイール エアロ シリアル<br>内装 色 傷B ヤブレ コゲ コゲ穴 オーディオ穴 車種 年式 月 日 最大積載量 Kg |            |               |            |                    |                                                 |          |          |          |          |          |          |              |            |               |            |                    |                                                 |