

2017 SUBARU Impreza Sport 2.0i-S EyeSight		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GT7	DISPLACEMENT 1,995 cc		
YEAR / REG. 2017/03	MILEAGE 20,467 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. GT7-011324	DIMENSIONS (L X W X H) 446 × 178 × 148 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Leather Seats Cruise Control	
INSPECTOR REPORT			
Exterior: Notable scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present. Repair history: No abnormalities in the structural components.			

ORIGINAL JAPANESE AUCTION SHEET

青森内のカー鑑定/JAAA鑑定証の発行と下記記載の評価は異なります

車種 H29 3月 インプレッサスポーツ	メーカー スバル	グレード 2.0 i-Sアイサイト	評価点 4
車種 GT7	年式 2000	燃料 ガソリン	内装 B
年式 10年3月	抹消 2010.4.17	マイル 467	4WD
カラー クォーツブルーパール	カラーNo. 11,870円	リサイクル料 GT7-011324	車台番号 GT7-011324
シフト フロア	AT	乗車定員 5人	長さ cm

車検返却日
(保証書・取説説明書等)

整備
エンジン
変速機
サスペンション
ブレーキ
ステアリング
その他

セールスポイント
本車シートがパワーシートCDがバックカメラ
ETC機能付きシステムスタートキーキーレス
エントリ(A)リモコンキーシステムバックサイド
エアバックはモリザビッドセグメントV電装
装備精洗ブレーキAWDガイドリングス
フルードヒーターブルーレイ再生DVD再生

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが低いほど、車体の状態が良いことを示します。ダメージレベルが高いほど、車体の状態が悪いことを示します。ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが低いほど、車体の状態が良いことを示します。ダメージレベルが高いほど、車体の状態が悪いことを示します。

クオリティグレード説明
外装: 劣化する平ズやヘコミは補修済みですが、小さな平ズやヘコミが残っています。
内装: 劣化する汚れ等が、部分的にあります。

修理歴: 骨格部に異常はありません。

車検返却の保証は、停止状態で実施できる範囲で行っています。