

2017 SUBARU Justy 1.0 G Smart Assist		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-M900F	996 cc		
YEAR / REG.	MILEAGE		
2017/06	128,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Brown	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M900F-0002346	370 × 167 × 174 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both...		Cruise Control	
INSPECTOR REPORT			
Seat scuffs, alloy wheel scratches			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/6月	メーカー スバル	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 3.5
車名 ジャスティ	グレード 1.0 G スマートアシスト	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 1000 cc	型式 DBA-M900F	通称 型式	内装 A・B・C
車検 - - - / - - -	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)	
走行 128,000 km	インパネ	CVT		
外装色 ブラウン	カラーNo. ()	エアコン	新車品のみ O印 を記入	
内装色 ()	乗車定員 5 人	PS	AW	サンルーフ
ハンド 左・右	輸入 区分	ディーラー	走行	ナビ
9,630 円		預託金	エブリック	TV
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/衝突被害軽減ブレーキ/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/横滑り防止装置 (E S C) /フルフラット/両側電動スライドドア				
検査記入欄				
シートレール AWキズ				
修復歴 有 . ()				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ G ガラスキズ				
W 補修跡 S サビ C 腐食 X 交換部 XX 交換所				
登録No. 月 日 までに名変できる方				
名変中				
車検番号 M900F-0002346				
FW トピ石 ()	ワレ	外装 ()	小 ()	エアロ
内装 ()	シタ	ヤブレ	コガ	コガ穴
シリアル No.				
長さ 幅 高さ 最大積重量				
cm cm cm Kg				