

ORIGINAL JAPANESE AUCTION SHEET

注意事項・不具合箇所

検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入

下回りサビ 室内汚れ シートスレ中

ハンドルスレ 室内内張傷

トリアミール ケズ ヒビ ワレ

工具 ㊦ ㊦



The diagram shows a top-down view of a vehicle chassis. It includes labels for various components: 'A1' for the front and rear suspension arms, 'U1' for the central differential or transmission area, and '6 mm' for the width of the front and rear tracks. A small circle with the character '欠' (Kaku, meaning 'missing' or 'defect') is located at the bottom right of the diagram.