

2017 SUBARU Levorg 1.6 STI Sport EyeSight		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-VM4	DISPLACEMENT 1,599 cc		
YEAR / REG. 2017/09	MILEAGE 39,599 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE SUV		
CHASSIS NO. VM4-105770	DIMENSIONS (L X W X H) 469 × 178 × 149 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Leather) Cruise Control		Sunroof Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Seat wrinkles, some interior scratches, top surface wrapping, exterior lacks luster.			

初年度登録		メーカー スバル		ドア数 5		ボディ形状 SUUV クロカン		特価点	
H29 9月		車名 レヴォーグ		グレード 1.6STスポーツアイサイト		駆動方式 2WD 4WD		4.5	
車種 自家用・その他（ ）		排気量 1500 CC		型式 DBA-VM4		燃費モード		内装 A・B・C	
年式 - - 年 / - - 月 / - - 日		燃料 ハイブリッド（ ）		ディーゼル		償とり返り（保証費・取扱説明書等）			
走行 口内にヤブガサシ（※交換）・（※盗損） 右前部は11月1日（※盗損） 左前部は11月1日（※盗損）		シフト AT							
外装色 ブルー		カラーNo. (K3X)		エンジン AD・6AO・WAG・()		装備品のみの O印 を記入			
()		内装色 ()		積算定員 5人		☐ EP ☐ F ☐ AN ☒ サブーフ ☐ 実用			
シモ 左・右 輸入区分		ディーラー ディーラー		走行 走行距離 13,610 km		ABS		キーレス	
セールスポイント						修復歴 有・無			
検査記入欄						A キズ B ヒキ C ヒキ D ヒキ E ヒキ F ヒキ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換済 登録地 No. _____ 月 _____ 日 _____ 日に各店まで来る 車体番号 VM4-105770			
シートシワ、ルーム内一部キズ、上面ラッピング、外装ツヤなし						PW ☒ シミ WR ☒ コゲ GR ☒ オイル ☒ エアロ ☒ 内装 ☒ シミ ヤブレ コゲ ゴカス オーディオ系 ☒ 劣化			