


2017 MAZDA Biente 2.0 20S SKYACTIV		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-CCFFW	DISPLACEMENT 1,997 cc		
YEAR / REG. 2017/03	MILEAGE 64,000 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. CCFFW-118058	DIMENSIONS (L X W X H) 472 × 177 × 184 cm		
SALES POINTS			
Alloy Wheels Side Camera Navigation System		Power Sliding Doors (Both Sides) (Both... Back Camera	
INSPECTOR REPORT			
Slight distortion in rear floor. Front windshield: scratches, stone chips, cracks, repair marks, replacement required. Interior: scratches, dirt, burns, holes, scuffs, tears.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成29年 3月	車名・グレード ビアンテ 20S-スカイアクティブ	2WD 4WD	評価点 (R)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-CCFFW	排気量 2000 CC	ドア 5 形状 V
		定員 8人 積載 kg	外装 内装 C B
車歴 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)	
車検 年 月 (日)	冷却 WAC	キーレススマートキー・ETC・バックモニター	
走行 6万4千000 km	燃料 ガソリン	HIDヘッドライト・パワースライドドア (両側)	
色 ブラック	色替 マイ	装備品 (純正品に限り○をつけてください)	
R券 14,110 円		(PS) (PW) (AB) (TB) AW	
注意事項申告欄		SR ナビ TV カワ	
	リアフロア歪み小	新車保証書 有・無	後日品
		有・無	
			
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	A-キズ E-エクゴ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
車台番号 118058		型式指定番号 参考	
登録番号		車検有効期 参考	