


2017 MAZDA CX-3 20S Noble Brown 4WD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-DKEAW	DISPLACEMENT 1,997 cc		
YEAR / REG. 2017/09	MILEAGE 53,780 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE SUV		
CHASSIS NO. 100534	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control		Leather Seats (Nappa Leather, Grand Lu... Navigation System	
INSPECTOR REPORT			
Right front instrument panel distortion, right center pillar pinch scratch.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/9月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クロカン	評価値 R
車名 CX-3	グレード 20S ノーブルブラウン 4WD	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 cc	型式 6BA-DKEAW	通称 A・B・C	内装 A・B・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 53,780 km	フロア	AT	後付選り品 (保証書・取扱説明書 等)	
外装色 グレー	カラーNo. ()	エアコン AG・AG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	EP	サンルーフ	シート
左・前 左・前	ディーラー・走行 11,010 円	エブリック	GS	TV
セールスポイント 純正ナビ・フルセグTV レーダークルーズコントロール ヘッドアップディスプレイ バックモニター ハーフレザーシート・シートヒーター パーキングセンサー LEDヘッドライト 純正18インチAW ETC ドライブレコーダー Dナビメモリーパワーシート スマートキー・プッシュスタート ※ナビSDカード後発送になります				
検査記入欄 右フィンパネ歪 右センターピラー挟み込みキズ		修復歴 G・無		
		A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修部 S サビ C 腐食 X 交換部 XX 交換済		
		登録No. 月 日 までに名義できる方		
		車体番号 100534		
FW トピ石 備A フレ 外装 小 A・曲 エアロ シリアル No.				
内装 内装 シミ ヤブレ コグ コグス オーディオス		車種 長さ cm 幅 cm 高さ cm 最大積載量 kg		