

2017 MAZDA CX-3 20S Proactive		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-DKEFW	DISPLACEMENT 1,997 cc		
YEAR / REG. 2017/07	MILEAGE 51,160 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE SUV		
CHASSIS NO. 100927	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Leather Seats Back Camera	
INSPECTOR REPORT			
Seat wrinkles, rear spoiler paint peeling.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/7月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クワカン	評価点 4
車名 CX-3	グレード 20Sプロアクティブ	駆動区分 2WD	4WD	
車歴 自用・その他()	年式 2000	型式 6BA-DKEFW	通称 2WD	内装 A・B・C
車検 -年-月/日	燃料 ガソリン	ディーゼル	後日進引品 (保証書・取扱説明書 等)	
走行 51,160 km	シフト フロア	AT		
外装色 ガンメタ	カラーNo. AG・BG・WAG・()	モーター	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	エアロ	サンルーフ	シート
左・前・後 11,010円	ディーラー 11,010円	走行 11,010円	エアロ	キーレス
セールスポイント				
純正ナビ・フルセグTV バックモニター CD/DVDプレーヤー ヘッドアップディスプレイ ハーフレザーシート LEDヘッドライト パーキングセンサー ドライブレコーダー スマートキー・プッシュスタート ナビSD欠				
検査記入欄				
シートシワ RスロイラーPハグ				
車体番号 100927				
修理歴 有・無				
A キズ U ヘッドランプ B キズ・ヘッド P 熱劣化・サビ Q ガラスキズ W 経年劣化 S サビ C 腐食 X 交換部 YX 交換部				
名義中 月 日 まで名義できる方				
車体重量 100927				
シリアル No.				
内装 ゴロ シェ ヤブレ コグ コグ穴 オーディオス				