

2017 MAZDA CX-5 2.2 XD PROACTIVE Diesel Turbo		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-KF2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2017/08	MILEAGE 50,471 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE SUV			
CHASSIS NO. KF2P-120374	DIMENSIONS (L X W X H) 455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior stains, light scratches, light dirt inside the cabin, console scratches, interior trim scratches, steering wheel wear, seat wear, touch-up paint marks			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H29 8月	メーカー マツダ 車名 CX-5	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4
車種 自家用・その他 ()	排気量 2200 CC	型式 LDA-KF2P	内装 A・B	
車検 8年8月	燃料 ガソリン ハイブリッド ()	シフト シフト	走行 50,471 km	フロア 6 AT
外装色 ディープリステルブルーマイカ	カラーNo. 42M	エアコン Qd・AAG・WAG・ ()	乗車定員 5人	装備品のみ ORP を記入
左・右 左・右	ディーラー ディーラー	走行 12,480円	オプション PS・PR・AR・サンルーフ・革シート・エレクトリック・ABS・G・TV・モーター	
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/LEDヘッドライト/横滑り防止装置(ESC)/DVD再生/ミュージックプレイヤー接続可/CD/サイドカメラ/バックカメラ/障害物センサー/M Tモード付き				
検査記入欄 外装しみ、うすい傷キズ 室内傷汚れ コンソール傷 室内内装傷 ハンドルすれ シートすれ中 タッチパネル				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済 登録No. 月 日 までにも見てみる方 車体番号 KF2P-120374 FW トピ石 傷A フレ 外装 小 A・U A・曲 A・フレ 内装 ヨゴレ シミ ヤブレ コガ コガ穴 オーディオ穴 スレ				
車検 長さ cm 幅 cm 高さ cm 最大積載量 Kg				