

2017 MAZDA CX-8 XD L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
KG2P	2,188 cc		
YEAR / REG.	MILEAGE		
2017/11	98,796 km		
DOORS	SEATS		
5	6		
TRANSMISSION	FUEL		
AT	Diesel		
STEERING	EXTERIOR COLOR		
Right	Black		
BODY TYPE			
SUV			
CHASSIS NO.	DIMENSIONS (L X W X H)		
KG2P-100167	490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Leather Seats (Nappa Leather)		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Side Camera	
Back Camera		360° Camera	
Navigation System		Bose Sound System (AUDIOMPILOT2 + C...	
INSPECTOR REPORT			

車種登録番号		メーカー		D/A後装		ボディ形状		駆動形式		年式区分	
H29 / 11月		マツダ		S		SUV/クロカン				新車品	
		C X-8		グレード XD シ		Lパッケージ		燃費区分 2WD 4WD		4.5	
車種 自動車 ・ その他 ()		排気量 2200 CC		型式 KGZP		運転形式		内装 A・B・C			
車検 - 年 月 / 日		燃料 ガソリン		変速機 ハバグシド ()		後付選用品 (保証書 ・ 取扱説明書 等)					
(口)ディーラー購入(※ 全席 ※ 他店入 ※ 名義)		シート		フロア 6 AT							
発行 [] 年 月 日		カラー 白		オプション							
外装色 ジェットブラックマイカ (41W)		内装色		標準仕立		新車品のみ O印 を記入					
()		名義車主 (口) ()		乗用者定員 6 人							
()		ディーラー ・ 販売		12,860円		支払方法					
セールスポイント											
純正ナビ											
全方位カメラ											
BOSEサウンド											
ブルセグBluetooth											
ステアリングヒーター											
パワーバックドア											
クリアランスソナー											
ブラインdspスポットモニター											
検査記入欄											
外装装備											
修復歴											
有、											
A キズ U ヘッドオンキ B キズヘッス P 熱傷ヤケイロ Q 塗装キズ W 補修跡 S サビ C 腐食 X 交換部 XX 欠損部											
登録年月											
月											
日											
車体番号											
KGZP-100167											
PW											
内装											