

2017 MAZDA CX-8 XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-KG2P	2,188 cc		
YEAR / REG.	MILEAGE		
2017/11	143,473 km		
DOORS	SEATS		
5	6		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
KG2P-100651	490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Leather Seats (Nappa Leather)		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Side Camera	
Back Camera		Navigation System	
INSPECTOR REPORT			
Interior scuffs, door mirror scratches			

初年度登録	メーカー マツダ	ドア数 5	ボディ形状 SUV/クロカン	駆動形式 後驱车					
H29 / 11月	車名 C X - 8	グレード X D L パッケージ	燃費 2WD 60	年式 4					
車種 自動車 ・ その他 ()	排気量 2200	型式 CC	3DA-KG2P	国産 A・B・C					
車検 8 年 1 1 月 / 抜消	燃料 ガソリン ハイブリッド ()	モーター AT	後付選り目 () ※車・取付等々 ()						
走行 1 4 3 7 3	シフト オート								
外装色 コン (42M)	エンジン AD・AAO・AG・()								
()	内装色 標準指定	乗員定員 6人							
左・前・右 ディーラー ・ 運行	リサイクル料 12,860円	関係機関 エフアップ	ABS ナビ	キーレス					
セールスポイント									
LEDヘッドライト、360度ビューモニター、Boseサウンドシステム、スマートシティブレーキサポート、ブラインドスポットモニタリング、リアパーキングセンサー、ルーフレール、パワーシート、シートヒーター									
検査記入欄									
ルームインスレ、ドアミラーキズ									
修復歴 有、⑤									
A	キズ	U	ヘッパ剥離	B	キズ・ヘッパ	D	熱変形・割伤	G	ガラスキズ
W	錆腐食	S	サビ	C	変質	X	交換済	XX	交換済
登録年月日 月 日									名義主
車体番号 KG2P-100651									
PW	①②③	備A	ワレ	内装	小	オイル	エアロ	シリアル	ナンバー
内装	④⑤	シミ	ヤブレ	コガ	コガ穴	オードイオス	A・ウレ		
重量 ⑥⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊀ ㊁ ㊂ ㊃ ㊄ ㊅ ㊆ ㊇ ㊈ ㊉ ㊐ ㊑ ㊒ ㊓ ㊔ ㊕ ㊖ ㊗ ㊘ ㊙ ㊚ ㊛ ㊜ ㊝ ㊞ ㊟ ㊠ ㊡ ㊢ ㊣ ㊤ ㊦ ㊧ ㊨ ㊩ ㊪ ㊫ ㊬ ㊭ ㊮ ㊯ ㊰ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿									