

|                                                                                                                                                                                            |                                              |                                                     |               |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-----------------------------------------------------|---------------|
| 2017 MAZDA Demio 1.3 13S Noble<br>Crimson                                                                                                                                                  |                                              | OVERALL<br>4                                        |               |
|                                                                                                                                                                                            |                                              | EXTERIOR<br>-                                       | INTERIOR<br>- |
| MODEL CODE<br>DBA-DJ3FS                                                                                                                                                                    | DISPLACEMENT<br>1,298 cc                     |                                                     |               |
| YEAR / REG.<br>2017/12                                                                                                                                                                     | MILEAGE<br>77,000 km                         |                                                     |               |
| DOORS<br>5                                                                                                                                                                                 | SEATS<br>5                                   |                                                     |               |
| DRIVETRAIN<br>2WD (FF)                                                                                                                                                                     | TRANSMISSION<br>AT                           |                                                     |               |
| FUEL<br>Petrol                                                                                                                                                                             | STEERING<br>Right                            |                                                     |               |
| EXTERIOR COLOR<br>Red                                                                                                                                                                      | BODY TYPE<br>Hatchback                       |                                                     |               |
| CHASSIS NO.<br>DJ3FS-500439                                                                                                                                                                | DIMENSIONS (L X W X H)<br>406 × 170 × 153 cm |                                                     |               |
| SALES POINTS                                                                                                                                                                               |                                              |                                                     |               |
| Alloy Wheels<br>Front Camera<br>Adaptive Cruise Control<br>Navigation System                                                                                                               |                                              | Pre-Collision Braking<br>Back Camera<br>360° Camera |               |
| INSPECTOR REPORT                                                                                                                                                                           |                                              |                                                     |               |
| Medium stone chips/dents, medium steering wheel wear, small console wear, exterior wrinkles, minor exterior scratches, front stone chips, small front glass stone chips, headlight fogging |                                              |                                                     |               |

[illegible]