

| 2017 MAZDA FLAIR WAGON CUSTOM<br>STYEL XS Dual Camera Brake Support                                                                                                                                      |                                              | OVERALL               |          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-----------------------|----------|
|                                                                                                                                                                                                          |                                              | 4.5                   |          |
|                                                                                                                                                                                                          |                                              | EXTERIOR              | INTERIOR |
|                                                                                                                                                                                                          |                                              | -                     | -        |
| MODEL CODE<br>MM42S                                                                                                                                                                                      | DISPLACEMENT<br>658 cc                       |                       |          |
| YEAR / REG.<br>2017/08                                                                                                                                                                                   | MILEAGE<br>23,768 km                         |                       |          |
| DOORS<br>5                                                                                                                                                                                               | SEATS<br>4                                   |                       |          |
| TRANSMISSION<br>AT                                                                                                                                                                                       | FUEL<br>Hybrid (Petrol)                      |                       |          |
| STEERING<br>Right                                                                                                                                                                                        | EXTERIOR COLOR<br>Silver                     |                       |          |
| BODY TYPE<br>Kei                                                                                                                                                                                         |                                              |                       |          |
| CHASSIS NO.<br>MM42S-593782                                                                                                                                                                              | DIMENSIONS (L X W X H)<br>340 × 148 × 174 cm |                       |          |
| SALES POINTS                                                                                                                                                                                             |                                              |                       |          |
| Alloy Wheels<br>Navigation System                                                                                                                                                                        |                                              | Pre-Collision Braking |          |
| INSPECTOR REPORT                                                                                                                                                                                         |                                              |                       |          |
| Exterior: Notable scratches and dents have been repaired, but small scratches and dents remain.<br>Interior: Some noticeable stains are present in parts. Repair history: No abnormalities in the frame. |                                              |                       |          |

[illegible]