

2017 MAZDA Scrum Van PA		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-DG17V		DISPLACEMENT 658 cc	
YEAR / REG. 2017/08		MILEAGE 139,557 km	
DOORS 5		SEATS 4	
TRANSMISSION MT		FUEL Petrol	
STEERING Right		EXTERIOR COLOR White	
BODY TYPE Minivan			
CHASSIS NO. DG17V-251544		DIMENSIONS (L X W X H) 340 × 148 × 190 cm	
INSPECTOR REPORT			
Interior dirt/scratches, exterior scratches/rust, minor stone chips, rust on right rear step, driver's side outer door handle loose, rear floor warped.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/		メーカー マツダ		ドア枚数 5		ボディ形状 バン		評価点 R																					
8月		車名 スクラム		グレード PA		駆動区分 2WD 4WD																							
車歴 自用・その他 ()		排気量 660 CC		型式 HBD-DG17V		通称 型式		内装 A・B・C																					
車検 9年9月 / 抹消		燃料 ガソリン		ディーゼル		後日送り品 (保証書・取扱説明書等)																							
走行 139,557マイル		インパネ 5 MT																											
外装色 ホワイト		カラーNo. (26U)		エアコン (A)・AAG・WAG・()		新備品のみ O印 を記入																							
()		内装色		乗車定員 4人		P3		PW AW サンルーフ 革シート																					
ハンド 左・右		輸入 区分		ディーラー・並行		リサイクル料 8,050円・預託金		エアバック (S) ナビ TV キーレス																					
セールスポイント ★5速MT★KENWOODラジオ★ETC																													
検査記入欄 内装汚れ擦れ 外装傷、錆 飛び石小 右リヤステップ錆 運転席外側ドアハンドル外れ気味 リヤフロア歪み					修復歴 0. 無																								
PW (ト) 備A フレ 外装 (A)・U (A)・曲 エアロ シリアル No.					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ・凹み</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・剥落</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>					A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・剥落	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコみ・凹み	B	キズ・ヘコみ	P	色あせ・剥落	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																				
登録No.					名義中																								
月 日					まで(に)名義できる方																								
車体 番号 DG17V-251544																													
内装 (ヨ) シミ ヤブレ コゲ コゲ穴 オーディオ穴 (S)					長さ 339 cm 幅 147 cm 高さ 189 cm 最大積載量 Kg																								