

2017 MITSUBISHI Delica D5 Active Gear		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-CV1W	DISPLACEMENT 2,267 cc		
YEAR / REG. 2017/09	MILEAGE 141,231 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. CV1W-1205109	DIMENSIONS (L X W X H) 473 × 179 × 187 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Sliding Doors (Both Sides) (Both... Back Camera	
INSPECTOR REPORT			
Headliner stains, interior trim damage, steering wheel wear, console scratches, seat sagging, aftermarket muffler.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		17497		0001		シリアナンバー		評価点	
H 29		デリカD5		5		グレード		4	
9月		LDA-CV1W		2,300 cc		燃料		2WD	
車種		乗用車		シフト		AT		AC	
走行距離		14,231 km		マイル		(交換)		SR	
外装色		7色(7)レータリッ		色替無		カラーNo.		TV	
車台No.		CV1W-1205109		色替無		カラーNo.		TV	
登録No.		抹消		14,710円		未償還		DVD	
定乗		7人		kg		473 cm		179 cm	
輸入車のみ		モデル		ディーラー		並行		左	
セーレスポイント		後席モニター		アルパインインナビ		バックカメラ		フルセグTV	
		クリアランスソナー		シートヒーター		ハーフレザーシート		オートクルーズコントロール	
		B i u e t o o t h接続							
注意事項・不具合箇所									
検査員記入欄：検査歴「有」の場合は検査箇所・交換箇所を記入									
天候汚れ									
室内汚損									
ハンドルすれ									
コンソール傷									
シートヘタリ									
社外マフラー									
ドアミラー		キズ		ヒビ		フレ			
上側		無		シヤッキ		無			