


2017 MITSUBISHI Delica D5 D Power Package		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-CV1W	DISPLACEMENT 2,267 cc		
YEAR / REG. 2017/09	MILEAGE 29,203 km		
DOORS 5	DRIVETRAIN 4WD		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Pearl White		
BODY TYPE Minivan			
CHASSIS NO. CV1W-1203756	DIMENSIONS (L X W X H) 473 × 180 × 187 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Power Sliding Doors (Both Sides) (Both... Navigation System	
INSPECTOR REPORT			
Exterior: small scratches, small dents. Interior: dirt, scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録	車 名	ドア・開閉	グ レード	駆動	総合評価		
29.9月	デリカD:5	5	D ハワーパッケージ	4WD	4.5		
型 式	排気量	燃料	車 種	定員(最大)		積載量(最大)	輸 入 車
LDA CV1W	2,200 _{CC}	軽油	自家用	8 名	Kg	車種名	
ミッション	エアコン	カラー名	外 装 色	装 備		保証書 取扱	内装評価
IAT	AAC	W23U25	パール2	PS 付	PW TV	17B ABS	B
走行距離	車 種	登録ナンバー	注 意 点		車 台 番 号	保証金	
29,203 _{Km}	年 月				CV1W-1203756	14,710 _円	
セールスポイント		特記事項・不具合箇所					
4WD・純正ナビ・フルセグTV 後席フリップダウンモニター クルーズコントロール 純正アルミホイール 両側パワースライドドア		外装 小キズ 小凹 内装 ヨゴレ キズ					
注 意 事 項							
スマートキー・パドルシフト シートヒーター・HIDヘッドライト							
							

△(キズ)・U(ヘコミ)・B(キズを伴うヘコミ)・W(傷痕跡)・D(変形跡)
※(錆)・C(腐食)・XX(交換済み)・X(要交換)・G(ガラス点キズ)