

|                                                                                                                                                                                           |                        |                       |          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------|----------|
| 2017 MITSUBISHI EK CUSTOM G Safety Package All-around Monitor                                                                                                                             |                        | OVERALL               |          |
|                                                                                                                                                                                           |                        | 3.5                   |          |
|                                                                                                                                                                                           |                        | EXTERIOR              | INTERIOR |
|                                                                                                                                                                                           |                        | -                     | -        |
| MODEL CODE                                                                                                                                                                                | DISPLACEMENT           |                       |          |
| B11W                                                                                                                                                                                      | 659 cc                 |                       |          |
| YEAR / REG.                                                                                                                                                                               | MILEAGE                |                       |          |
| 2017/05                                                                                                                                                                                   | 47,600 km              |                       |          |
| DOORS                                                                                                                                                                                     | SEATS                  |                       |          |
| 5                                                                                                                                                                                         | 4                      |                       |          |
| TRANSMISSION                                                                                                                                                                              | FUEL                   |                       |          |
| AT                                                                                                                                                                                        | Petrol                 |                       |          |
| STEERING                                                                                                                                                                                  | EXTERIOR COLOR         |                       |          |
| Right                                                                                                                                                                                     | Silver                 |                       |          |
| BODY TYPE                                                                                                                                                                                 |                        |                       |          |
| Kei                                                                                                                                                                                       |                        |                       |          |
| CHASSIS NO.                                                                                                                                                                               | DIMENSIONS (L X W X H) |                       |          |
| B11W-0302290                                                                                                                                                                              | 340 × 148 × 162 cm     |                       |          |
| SALES POINTS                                                                                                                                                                              |                        |                       |          |
| Alloy Wheels                                                                                                                                                                              |                        | Pre-Collision Braking |          |
| Front Camera                                                                                                                                                                              |                        | Side Camera           |          |
| Back Camera                                                                                                                                                                               |                        | 360° Camera           |          |
| INSPECTOR REPORT                                                                                                                                                                          |                        |                       |          |
| Exterior: Noticeable scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present in parts. Repair history: No abnormalities in the frame. |                        |                       |          |

[illegible]