

2017 Nissan Note e-POWER 1.2 e-POWER Nismo		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DAA-HE12	DISPLACEMENT 1,198 cc		
YEAR / REG. 2017/02	MILEAGE 45,031 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. HE12-033952	DIMENSIONS (L X W X H) 416 × 169 × 153 cm		
SALES POINTS			
Alloy Wheels Back Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Door mirrors have scratches. Steering wheel shows wear. Seats are sagging. Front windshield has scratches, stone chips, cracks, repair marks, and needs replacement. Interior has scratches, stains, burns, holes, scuffs, tears, and rips.			

初度登録年月 平成 29 年 2 月	車名・グレード ノート[®] ワー e1[®] ワーンスモ	2WD 4WD	評価値点 (4)				
ディーラー・並行 モデル年式 年 ハンドル 左・右	型式 DAA-HE12	排気量 1200 CC	ドア 5 形状 箱型 定員 5人 積載 kg				
車種 自家用		シフト FAT					
車検 年 月 (日) 走行 4万5千 031 km		冷房 AAC					
色 パール 色替 色コード QAB		燃料 その他					
R券 7,890 円							
注意事項申告欄 外装 小A・小U ドアミラー キズ ハンドル すれ シート へたり							
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">フロントガラス</td> <td style="width: 25%;">キズ・破ヒビ割・リペア跡・X要</td> <td style="width: 25%;">内装</td> <td style="width: 25%;">キズ・汚レ・コゲ・穴・ズレキレ・破レ</td> </tr> </table>				フロントガラス	キズ・ 破 ヒビ割・リペア跡・X要	内装	キズ・汚レ・コゲ・穴・ ズレ キレ・破レ
フロントガラス	キズ・ 破 ヒビ割・リペア跡・X要	内装	キズ・汚レ・コゲ・穴・ ズレ キレ・破レ				
車台番号 033952 登録番号 033952							