

2017 Nissan Serena 2.0 Highway Star V Selection		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-GFC27	DISPLACEMENT 1,997 cc		
YEAR / REG. 2017/11	MILEAGE 82,000 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Minivan		
CHASSIS NO. GFC27-074824	DIMENSIONS (L X W X H) 477 × 174 × 187 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Front Camera Back Camera Navigation System		Power Sliding Doors (Both Sides) (Both... Cruise Control Side Camera 360° Camera	
INSPECTOR REPORT			
Front glass: Scratches, stone chips, cracks, repair marks, replacement/major repair required. Interior: Scratches, dirt, burn holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成29年11月	車名・グレード セレナ ハイウェイスター Vセレクション	2WD 4WD (4)	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DAA-GFC27	排気量 2000 CC	ドア 5 形状 V
		定員 8人	積載 kg
車庫 自家用	シフト CVT	セールスポイント (正常に機能するものに限りです)	外装 C
車検 年 月 (日)	冷却 WAC	純正9インチナビ (NMS17D-L)・フリップダウンモニター	内装 C
走行 8万1千100 km	燃料 ガソリン	アラウンドビューモニター・フルセグTV・DVD再生	
色 レッド2	色替 XAN	ドライブレコーダー・両側パワースライドドア	
R券 10,190 円		装備品 (純正品に限り○をつけてください)	
注意事項申告欄		(PS) (PW) (BS) (AB) (AW) (SR) (4H) (TV) カワ	
		新車保証書 有・無	
		後日品	
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要			
内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ			
車台番号 074824			
登録番号			

スベア

A-キズ	E-エクボ	U-凹み	W-補修跡	S-サビ	C-腐食	XX-交換済
型式指定番号 ※ 参考	識別区分番号 ※ 参考	車検証取得 ※ 参考	長さ	幅	高さ	重量