

2017 Nissan Serena Highway Star		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-GFC27	DISPLACEMENT 1,997 cc		
YEAR / REG. 2017/06	MILEAGE 58,837 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Station Wagon		
CHASSIS NO. GFC27-057463	DIMENSIONS (L X W X H) 477 × 174 × 187 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Trunk replaced, panel dented/repaired.			

初年度登録	メーカー	日産	ドア数	5	ボディ形状	ステーションワゴン	評価点																																																		
H29 / 6月	車名	セレナ	グレード		駆動区分	4WD	R																																																		
車種	良薬用・その他()	排気量	2000 CC	型式	DAA-GFC27	運転形式	A・B・C																																																		
車検	10年6月	抹消	燃料	ガソリン	ディーゼル	後日選召品(保証書・取扱説明書等)																																																			
走行	口内にマークを記入(※交換 ※盗損 ※失窃) シフト + 万 千 百 十 マイル 58,837	フロア AT	内装色	カラーNo.	Eアエノン AG・WG・WAC・()	装備品のみの印を記入																																																			
()	自賠保は1年内に「仮償」を記入	内装色	クロ系	標準定員	8人	Fg Fw AW サンプル 革シート																																																			
ハンドル	左・右	ディスター	進行	10,190円 + 預託金	エアロック	Gb Gf Gv Gx	モース																																																		
セールスポイント				 修復歴 ②、無																																																					
検査記入欄				<table border="1"> <thead> <tr> <th>A</th> <th>劣化</th> <th>U</th> <th>へこみ割れ</th> <th>B</th> <th>劣化へこみ</th> <th>P</th> <th>熱変性・ボロボロ</th> <th>G</th> <th>ガラスノズ</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>腐蝕部</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> <tr> <td>登録時</td> <td>春日部</td> <td>301</td> <td>む</td> <td>9380</td> <td>名義</td> <td colspan="4"></td> </tr> <tr> <td>車体番号</td> <td colspan="9">月 日 までは名義である</td> </tr> <tr> <td>事故修理</td> <td colspan="9">GFC27-057463</td> </tr> </tbody> </table>				A	劣化	U	へこみ割れ	B	劣化へこみ	P	熱変性・ボロボロ	G	ガラスノズ	W	腐蝕部	S	サビ	C	腐食	X	交換済	XX	交換済	登録時	春日部	301	む	9380	名義					車体番号	月 日 までは名義である									事故修理	GFC27-057463								
A	劣化	U	へこみ割れ	B	劣化へこみ	P	熱変性・ボロボロ	G	ガラスノズ																																																
W	腐蝕部	S	サビ	C	腐食	X	交換済	XX	交換済																																																
登録時	春日部	301	む	9380	名義																																																				
車体番号	月 日 までは名義である																																																								
事故修理	GFC27-057463																																																								
トランク交換 飛んだパネル板金																																																									
FW	トビ石	傷A	フレ	外装	小 A・U	ホイール A・曲	エアロ シリアル No.																																																		
内装	ヨゴレ	シミ	ヤブレ	コゲ	コガケ	オーデイオス	スレ																																																		
				車両	台数	477	価	174	減価	186	最大積重量																																														