

2017 Nissan Serena Highway Star G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GFC27	DISPLACEMENT 1,997 cc		
YEAR / REG. 2017/01	MILEAGE 83,353 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Minivan		
CHASSIS NO. GFC27-012013	DIMENSIONS (L X W X H) 477 × 174 × 187 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Adaptive Cruise Control 360° Camera		Power Sliding Doors (Both Sides) (Both... Cruise Control Back Camera Navigation System	
INSPECTOR REPORT			
Rear floor repaired			


年式登録番号 H29 / 1月		日産 セレナ		ドア数 5		ボディボックス ミニバン/ワンボックス		駆動形式 R	
車名		グレード ハイウェイスター G		車検区分 2WD 4WD					
車種 自動車 ・ その他 ()		排気量 2000 CC		型式 GFC27		運転方式		内装 A・C・G	
車検 - 年 / 月 / 日		納期 ガソリン ディーゼル ハybrid ()		後付選り品 (保証書・取扱説明書等)					
走行 (口)にマークを記入(左・右発) ●(追加の車・年検)		燃料 シュート							
[] 万 [] 千 [] 百 [] 十 [] 円		マイル フロア AT							
外観色 カラーストーン		エンジン QD・AAD・WAD・()		新着商品の O印 を記入					
マルーンレッド E I (XAN)		()		乗員定員 8人					
()		内装色		サドルフ 革シート					
左・前・後		ディーラー・運行		サイズ表示 81cm		エアバッグ		安全装置	

セールスポイント

両側パワースライドドア
純正ナビ
ブルーセグBlueboth
アラウンドビューモニター
パーキングアシスト
フリップダウンモニター
クリアランスセンサー

検査記入欄

リヤフロア修正



修正履歴

①、無

A	ボディ	U	ヘッドランプ	B	キズへず	H	色あせ・汚れ	G	ガラスキズ
W <td>修繕跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>変質</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td>	修繕跡	S	サビ	C	変質	X	交換済	XX	交換済

登録年月 月 日 家で自宅でも可

車体番号 GFC27-012013

PW	()	備A	フレ	内装	小	オイル	エアロ
					●・◎	◎・△	△・○
内装	()	シロ	ヤブ	コガ	コガ穴	オーデイオ	その他