


2017 Renault Twingo Intense One Owner Electric Open Soft Top Navigation Backup Camera Corner Sensor		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-AHH4B	DISPLACEMENT 897 cc		
YEAR / REG. 2017/02	MILEAGE 10,210 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (RR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. VF1AHB22AG0750967	DIMENSIONS (L X W X H) 362 × 165 × 154 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Sunroof Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29 2月	メーカー ルノー 車名 トゥインゴ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5																				
車種 自家用・その他 ()	排気量 890 cc	型式 DBA-AHH4B	通称 2WD	内装 A・B・C																				
年 -	月 -	日 -	燃料 ガソリン	変速機 AT																				
走行 10,210 km	シフト フロア	AT	後日取り込み ()																					
外装色 ホワイト	カラーNo. ()	エンジン AG・AG・WAG・()	整備品のみ O印 を記入																					
内装色 ()	乗車定員 4人	安全装置 ()	サッシュ	革シート																				
左・右 左	輸入区分 デ	走行 12,470円・預託金	エアロ	ナビ																				
セールスポイント ・ワンオーナー車 ・電動オープンソフトTOP ・パナソニックナビ ・TV ・バックカメラ ・パーキングセンサー ・アイドリングストップ ・クルーズコントロール ・ステアリングスイッチ ・オートライト ・LEDポジション ・フォグランプ ・15インチAW ・ドアバイザー ・Bluetooth ・USB																								
検査記入欄 																								
修復歴 有・無																								
<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>					A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録No. () 月 () 日 までに名変できる方																								
名変中																								
VF1AHB22AG0750967																								
シリアル No. ()																								
車種 362 cm 165 cm 154 cm 最大積載量 kg																								