


2017 Suzuki Alto 5D L		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HA36S	DISPLACEMENT 658 cc		
YEAR / REG. 2017/08	MILEAGE 7,500 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. HA36S-337167	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Document delivery takes approximately 10 days post-contract. Exterior repainted to a specified color. Interior is dirty. Rust present in the engine room. Core support has a U-shaped dent. Pillar inner shows rust. Undercarriage has C2-grade rust.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29/8月	メーカー スズキ	ドア枚数 5	ボディ形状 軽四	評価点 3.5
車種 自家用・その他 ()	車名 アルト	グレード L	駆動方式 4WD	
走行 7,500 km	排気量 660 cc	型式 DBA-HA36S	内装 A・B・C	
燃料 ガソリン	変速機 AT	ディーゼル	後日選り品 (保証書・取扱説明書等)	
外装色 スズケン	カラーNo. AAG・WAG・()	エアコン	装備品のみのO印を記入	
内装色 ()	皮革シート	サンルーフ	革シート	
左・右 左・右	ディーラー	走行 7,500 km	エレクトロニック	ナビ TV キーレス
セールスポイント				
検査記入欄		修復歴 有・無		
精細送付は成約後10日以内となります。 指定色 外装のみ色替え 室内汚れ エンジンルーム内サビ コアサポーターU ピラーインナーBU 下回りC2		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・傷 G ガラスキズ W 燃焼跡 S サビ C 腐食 X 交換部 XX 交換済 売却日 月 日 までに名義できる方 車体番号 HA36S-337167 シリアル No. FW 1234567890 フレ 外装 小 ホイル エアロ ① ② ③ ④ ⑤ A・フレ 内装 ⑥ シミ ヤブレ コガ コガ穴 オーディオA ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿		