

2017 Suzuki Alto Lapin 660 X		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-HE33S	658 cc		
YEAR / REG.	MILEAGE		
2017/01	52,005 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Yellow	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
HE33S-153319	340 × 148 × 153 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Front Camera		Back Camera	
360° Camera		Navigation System	
INSPECTOR REPORT			
Right rear instrument panel distortion. Partial scuffs and dirt inside the cabin. Various scratches and dents.			

印字位置確認 H29 1月		メーカー スズキ 車名 アルトラパン		ドア後取 S ボディ塗装 コンバクトハッチバック		評価点 R	
車種 自家用・その他()		排気量 660		CC CC		型式 DBA-HE33S	
年次 10年		月 1 / 注消		燃料 ガソリン		ディーゼル	
走行 10万		52,005 km		インパネ CVT		養護管理品 (保証書、取扱説明書等)	
外装色 イエロー-II		カラーNo. (2BR)		エアコン		装備品のみのO印を記入	
内装色 ()		撮影写真 4人		(P) (P) (A)		サルフェン	
左 左		右 右		エアロック		(TV)	
輸入国 タイ		ディーラー 東行		リサイクル料金 7,950円		登録料 500円	
セールスポイント							
内外装仕上済/キーレスエントリー/ABS/運転席エアバック/助手席エアバック/メモリーナビ付/フルセグTV/衝突被害軽減ブレーキ/アイドリングストップ/スマートキー/盗難防止システム/HID・キセノン・ディスプレイ/横滑り防止装置(EESC)/シートヒーター/バンチシート/DVD再生CD全周囲カメラ							
検査記入欄							
右Rインパネビズミ ルーム内スレ汚れ部分の 各キズ凹							
修復歴 ☒ 無							
台帳No. _____ 月 _____ 日 _____ に名で査定できる							
HE33S-153319							
FW トビロ 備A フレ 内装 小 A・G ホイール コガス オートボス スレ エアロ シリル 高							
内装 トヨロ ショ ヤレン コガ コガス オートボス スレ 車種 高							