

2017 Suzuki Jimny Land Venture		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE JB23W	DISPLACEMENT 658 cc		
YEAR / REG. 2017/02	MILEAGE 44,021 km		
DOORS 3	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Kei		
CHASSIS NO. JB23W-762479	DIMENSIONS (L X W X H) 340 × 148 × 168 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Driver's seat minor wrinkles, minor scratches on door trim and console, minor stone chip on front glass, minor scuffs on driver's seat and steering wheel.			

ORIGINAL JAPANESE AUCTION SHEET

H29 / 2月		メーカー スズキ		ドア枚数 3	ボディ形状 軽四	評価点 4																				
車名 ジムニー		グレード ランドベンチャー		駆動区分 2WD	4WD																					
車種 自家用・その他 ()	排気量 660 CC	型式 JB23W	通称 型式	内装 A・B・C																						
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検定通り品 (保証書・取扱説明書 等)																							
走行 44,021 km	シフト フロア 4	AT																								
外装色 ブラックパール	カラーNo. ()	エアコン	装備品のみ ORP を記入																							
()	内装色 ()	Qd・AAG・WAG・()	乗車定員 人	PS	サンルーフ	革シート																				
左・右	ディーラー・並行	9,010円	円・預託金	エブリック	ナビ	TV																				
セールポイント																										
CD/運転席エアバック/キーレスエントリー/A B S/助手席エアバック/4WD/シートヒーター/ミュージックプレーヤー接続可			修復歴 有・無																							
検査記入欄			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
運転席しわく小 ドア内張りA<小> コンソールA<小> Fガラス飛び石<小> 運転席すれく小 ハンドルすれく小			登録No. 月 日 までにも変更できる方 車体番号 JB23W-762479 シリアル No.																							
FW	トビ石	傷A	フレ	外装	小	ホイール	エアロ																			
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ	長さ	幅																	
								高さ	最大積重量																	
								cm	Kg																	