

2017 Suzuki Solio 1.2 Hybrid MZ		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-MA36S	DISPLACEMENT 1,242 cc		
YEAR / REG. 2017/04	MILEAGE 41,000 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Hybrid (Petrol)		
STEERING Right	EXTERIOR COLOR Pearl White		
BODY TYPE Hatchback			
CHASSIS NO. MA36S-155119	DIMENSIONS (L X W X H) 371 × 163 × 175 cm		
SALES POINTS			
Alloy Wheels Cruise Control 360° Camera		Power Sliding Doors (Both Sides) (Both... Back Camera Navigation System	
INSPECTOR REPORT			
Minor wear on interior trim (grade A), small stone chip on front windshield.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29 4月	メーカー スズキ 車名 ソリオ	ドア数 5	ボディ形状 コンパクトハッチバック	評価点 4
車種 乗用車・その他 ()	排気量 1200 CC	型式 DAA-MA36S	駆動方式 2WD	4WD
車検 - - 年 月 / 日	燃料 ハイブリッド ()	ディーゼル シフト	後日選り込み (保証書・取扱説明書 等)	
走行 41,000 km	インパネ	CVT		
外装色 パール	カラーNo. ()	QD・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	()	サンルーフ	車シート
左・右 左・右	ディーラー 走行	9,770円	エレクトリック	ABS
セールスポイント キーレスエントリー/ABS/運転席エアバック/助手席エアバック/メモリーナビ他/フルセグTV/ワンオーナー/ETC/アイドリングストップ/スマートキー/オートクルーズコントロール/LEDヘッドライト/シートヒーター/フロントカメラ/サイドカメラ/バックカメラ				
検査記入欄 内装内張A小 Fガラス飛び石小				
修理歴 有・無 ()				
A ネズ U ヘッドランプ B キズ・ヘコ P 熱劣化・サケ Q ガラスキズ W 経年劣化 S サイズ C 腐食 X 交換部 YX 交換済 登録No. 月 日 まで有効である方 車体番号 MA36S-155119				
FR トボ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ	シリアル No.			
内装 右シ座 シス ヤブレ コグ コグ穴 オーディオ穴 スレ	長さ cm	幅 cm	高さ cm	最大積載量 kg