

2017 Suzuki XBEE Hybrid MX		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DAA-MN71S	996 cc		
YEAR / REG.	MILEAGE		
2017/12	46,150 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MN71S-101098	376 × 167 × 171 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Navigation System			
INSPECTOR REPORT			
Minor scratches on exterior, light stains and minor scratches inside.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H29 12月	メーカー スズキ	ドア枚数 5	ボディ形状 SUV/クロカン	評価値 4.5
車名 クロスビー	グレード ハイブリッドMX	駆動区分 4WD		
車種 自家用・その他 ()	排気量 1000 CC	型式 DAA-MN71S	通称 4WD	内装 A・B・C
車検 8年12月	抹消	燃料 ガソリン	ディーゼル	後日選り品 (色選り・取扱説明書 等)
走行 46,150 km	インパネ	AT		
外装色 スピードブルーメタリックII (C7R)	カラーNo. (C7R)	エアコン	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ	革シート	
左・前・後 左・前・後	ディーラー	走行	リサイクル料	9,750円・預託料
セールスポイント				
☆メモリーナビ・TV・CD☆ETC☆スマートキー2 個☆デュアルセンサーブレーキ☆パーキングセンサー☆ F席シートヒーター☆LEDライト☆16AW☆2ト ンルーフ				
検査記入欄				
外装小キズ 室内うす汚れ・小キズ				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 名義中				
車体番号 MN71S-101098				
FW トビ石 傷A フレ 外装 小 A・U A・曲 エアロ シリアル No.				
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ 車輪 傷 腐 剥離 最大積載量 Kg				