

2017 Toyota Esquire Gi Black Tailored 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-ZRR85G	1,986 cc		
YEAR / REG.	MILEAGE		
2017/03	105,839 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Other		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZRR85-0074371	469 × 169 × 186 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Pre-Collision Braking		Cruise Control	
Navigation System			
INSPECTOR REPORT			
Exterior iron powder adhesion, minor scratches on various parts, minor underbody rust, dirty interior, damaged steering wheel grip, minor lower bumper scratches.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		登録番号 17699	納品番号 0113	シリアル番号	評価点
年 月 日	車名	グレード	駆動	4	
H 29	エスクァイア	5	2WD		
3月	型式 DBA-ZRR85G	排気量 2,000 cc	燃料 ガソリン	A B C	
車種	年 月 日	車況	自用	シフト	CVT
走行距離	105,839 km	マイル (交換)	非 (不明)	冷却	AC
外装色	ホワイトパールクリスタルシャイン	色替無	カラーNo.	内装色	
車台No.	ZRR85-0074371	高圧電圧	月 日	純正装備品 ○をつける	
登録No.	抹消	リサイクル料 納付金	12,500円納付済	未納	
定員	7 (人)	重量	kg	満員	469 cm
輸入車のみ	モデル 型式	輸入国	ディーラー	並行	ハンドル 左
セールスポイント					
注意事項・不具合箇所					
検査員記入欄: 検査票「有」の場合は検査箇所・交換箇所を記入					
外装鉄粉付着					
各部S					
下廻りAU					
室内汚れ					
ハンドルグリップ不良					
バンパー下A					
ドアミラー	キズ	ヒビ	汚れ		
上側	②	シヤッキ	②		

