


2017 Toyota Harrier Progress		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ZSU60W	DISPLACEMENT 1,986 cc		
YEAR / REG. 2017/07	MILEAGE 36,645 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. ZSU60-0126454	DIMENSIONS (L X W X H) 473 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Front Camera Back Camera Navigation System		Power Tailgate Adaptive Cruise Control Side Camera 360° Camera JBL Premium Sound System (8-channel...	
INSPECTOR REPORT			
Left center pillar repaired.			

ORIGINAL JAPANESE AUCTION SHEET

H29 / 7月	メーカー トヨタ	ドア数 5	ボディ形状 SUV/クロカン	評価点 R
車名 ハリアー	グレード プログレス	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 cc	型式 ZSU60W	登録区分 A・⑤・C	
走行 36,645 km	燃料 ガソリン	変速機 AT	後付選用品 (保証書・取扱説明書 等)	
外装色 スパーリングブラックメタリックパールクリスタルシャイン	カラーNo. 220	エアコン ④・AAG・WAG・()	新着品のみ・O印を記入	
内装色 ()	乗車定員 5人	⑤	サンルーフ	革シート
① 左・② 輸入品	ディーラー・直行	12,550円	③ エアロ	④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩
セールスポイント		修復歴 ④・無		
JBLサウンド メーカーナビ フルセグBluetooth 全方位カメラ 衝突軽減ブレーキレーンアシスト レーダークルーズコントロール クリアランスソナー パワーバックドア ハーフレザーシート				
検査記入欄		A キズ B ハコボケサレ C キズ・ヘコミ D 色あせ・汚れ E ガラスキズ W 腐食跡 S サビ C 腐食 X 交換済 XX 交換済		
左センターピラー修理		名義中 月 日 まで ZSU60-0126454		
① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩	⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳	⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿		