

2017 Toyota HIACE VAN 3.0 Super GL		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE LDF-KDH206V	DISPLACEMENT 2,982 cc		
YEAR / REG. 2017	MILEAGE 85,644 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. KDH206-8116965	DIMENSIONS (L X W X H) 469 × 169 × 198 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Hood and front windshield have stone chips. Headlights are faded. Front bumper has a dent. Right side (front door, rear door, rear fender, back door, rear bumper) has scratches. Left side (rear fender, rear door, front door) has scratches, and the left rear fender has stone chips. Right rear tire has peeled lettering. Left rear wheel has curb rash. Driver's seat has wrinkles.			

初年度登録	メーカー	トヨタ	ドア数	5	ボディ形状	ミニバン/ワンボックス	評価点	
H29 / 二月	車名	ハイエースバン	グレード	3.0 スーパーGL	燃料区分	2WD ガソリン	4	
車種	自動車 / その他 ()	排気量 2980	型式	CC	LDF-KDH206V	国産車	内装	A ⑨ C
車検	- 年 月 / 日	燃料 ガソリン	変速機	5速MT	費用項目書 (保証書・取扱説明書 等)			
走行	走行距離 85,644 km	燃料 ハイブリッド	シート	AT				
外装色	ブラック	エアコン	④B・AAG・WAG・()	装備品のみのO印を記入				
内装色	()	車庫裏	人	PS	PW	AW	サンルーフ	革シート
左 / 右	ディーター	走行	9,550円 / 月	エアバック	ABS	TV	キーレス	
セールスポイント								
検査記入欄 ・ボンネット、フロントガラス：覆ひ付 ・ヘッドライト：点検済 ・フロント/リカバー：へこみ ・右側（フロントドア・リアドア・リアフェンダー・バックドア・リアカバー）：破損 ・左側（リアフェンダー・リアドア・フロントドア）：破損、リアフェンダーは覆ひ付あり ・右リアタイヤ：文字は消滅 ・左リアタイヤ：文字は消滅 ・左リアホイール：ガリ傷 ・左リアホイールにシワがひびき付いています。								
修復歴 有：⑥								
検査No. 月 日 年 名義人								
車検番号 KDH206-8116965								
車検No. 469 年 169 月 198 日 最大積載量								