


2017 Toyota Passo XS		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
M700A	996 cc		
YEAR / REG.	MILEAGE		
2017/07	36,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
M700A-0078431	365 × 167 × 153 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, minor exterior scratches and light scratches, AA grade 4 acquisition, wheel cover A, partial exterior fading.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H29 / 7月	メーカー トヨタ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 パッソ	グレード XS	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 1000 CC	型式 M700A	通称 型式	内装 A・B・C
燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)		
走行 36,000 km	インパネ	AT		
外装色 パウダリーページュメタリック	カラーNo. ()	エアコン Qb・AAG・WAG・()	装備品のみ ORP を記入	
内装色 ()	乗車定員 5 人	PS	AW	サンルーフ
ナビ ()	輸入 区分	ディーラー	走行	8,190 円・預託金
セールスポイント 横滑り防止装置 (ESC) / 運転席エアバック/キーレス エントリー/ABS/助手席エアバック/メモリーナビ他/衝突 被害軽減ブレーキ/衝突安全ボディ/アイドリングス トップ/ベンチシート				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価4点仕入れ ホイールカバーA 外装一部色あせ		修復歴 有・無 A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済 登録No. 月 日 までに名義できる方 車体 番号 M700A-0078431 FW (トビ) 傷A フレ 外装 小 (B・C) ホイル A・曲 エアロ シリアル No. 内装 (C) シス ヤブレ コガ コガ穴 オーディオ穴 (D) 長さ 幅 高さ 最大積載量 cm cm cm Kg		