

2017 Toyota Prius 1.8 A Touring Selection		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-ZVW51	DISPLACEMENT 1,797 cc		
YEAR / REG. 2017/02	MILEAGE 111,328 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. ZVW51-8032354	DIMENSIONS (L X W X H) 454 × 176 × 147 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Parking Assist (Auto Steering)		Modellista Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Interior minor dirt and scratches, seat scuffs, wheel scratches, various dents.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		車両番号	18208	納期	0005	シリアル番号		評価点	
年	月	日	車名	トア	グレード	駆動		3.5	
H 29			プリウス	5	1.8A ツーリングセレクション	4WD			
2	月		型式	DAA-ZVW51	排気量	1,800 cc	燃料	ガソリン	軽油
車検	R 10	3	車種	自家用	シフト	CVT	冷房	AC	
走行距離	1	1	3	2	8	マイル	4	5	km
外装色	白	黒	銀	青	赤	黄	緑	紫	その他
車台No.	ZVW51-8032354	カラーNo.		内装色		名義		月	日
登録No.	成田	リサイクル	11,480円	納税済	未納税	HDD	DVD	SD	
定員	5人	積載量	454 kg	長さ	176 cm	DVD再生可	CD		
輸入車のみ	モデル	年式	輸入国	ディーラー	走行	ハンドル	左	右	
セーレスポイント	モデリスタフルエアロ/熱線車/純正ナビ/フルセグ/Bカメラ/クルコン/デジタルインナーミラー/温感黒革シート/								

注意事項・不具合箇所

検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入

ルーム内汚損、傷

シートスレ

ホイールキズ

各キズ凹

U1

U2

U3

U4

U5

U6

U7

U8

U9

U10

U11

U12

U13

U14

U15

U16

U17

U18

U19

U20

U21

U22

U23

U24

U25

U26

U27

U28

U29

U30

U31

U32

U33

U34

U35

U36

U37

U38

U39

U40

U41

U42

U43

U44

U45

U46

U47

U48

U49

U50

U51

U52

U53

U54

U55

U56

U57

U58

U59

U60

U61

U62

U63

U64

U65

U66

U67

U68

U69

U70

U71

U72

U73

U74

U75

U76

U77

U78

U79

U80

U81

U82

U83

U84

U85

U86

U87

U88

U89

U90

U91

U92

U93

U94

U95

U96

U97

U98

U99

U100

ドアミラー

キズ

ヒビ

ウレ

工数

無

ジャッキ

無